

# Tool case MC4

Plastic case with tools for assembly of PV-KxT4 connectors



Assembly instructions  
download

Pos.	Order No.	Type	Description	Assembly instructions
	<b>32.6128-22100</b>	PV-WZ/AWG-SET-22100	includes basic content + crimping pliers PV-CZM-22100 (open contacts 12/10 AWG, closed contacts 8 AWG)	
	<b>32.6128-23100</b>	PV-WZ/AWG-SET-23100	includes basic content + crimping pliers PV-CZM-23100 (closed contacts 14/12/10/8 AWG)	
	<b>32.6128-00000</b>	PV-WZ/AWG-SET	includes basic content (crimping pliers not included)	

**Basic content**

1	<b>32.6058</b>	PV-MS-PLS	Assembly and unlocking tool	MA270
2	<b>32.0065</b>	PV-WZ-Torque-Set	Torque tool	MA231
3	<b>32.6027-128</b>	PV-AZM-128	Stripping pliers (cable sizes 12/10/8 AWG)	MA267
4	<b>32.6080</b>	PV-WZ-KS	Cable cutter	MA705
5	<b>32.6028</b>	PV-PST	Test plug	MA231
6	<b>32.0716</b>	PV-BVK4	Sealing cap for female cable couplers (10 pcs.)	MA258
7	<b>32.0717</b>	PV-SVK4	Sealing cap for male cable couplers (10 pcs.)	MA258

**Optional content (can be ordered separately)**

8	<b>32.6021-22100</b>	PV-ES-CZM-22100	Crimping die (open contacts 12/10 AWG, closed contacts 8 AWG)	MA251, MA231
8	<b>32.6021-23100</b>	PV-ES-CZM-23100	Crimping die (closed contacts 14/12/10/8 AWG)	MA251, MA231
9	<b>32.6055</b>	PV-LOC-B	Locator (for use with crimping die PV-ES-CZM-22100)	MA251
9	<b>32.6074</b>	PV-LOC-D	Locator (for use with crimping die PV-ES-CZM-23100)	MA251